

FIG. 1




FIG. 2




FIG. 3




FIG. 4





FIG. 5



FIG. 6

206T20" 6F28400T



MEASURED INSERTION LOSS (dB)

FIG. 7

205720" 6T43200T




FIG. 8

EFFECT OF THERMAL BALLS, THERMAL VIAS AND GROUND PLANE
ON THERMAL PERFORMANCE OF THE PACKAGE




FIG. 9